

- 3. DO NOT PRUNE TREE HEAVILY AT PLANTING. PRUNE ONLY CROSSOVER LIMBS, CO-DOMINANT LEADERS, AND BROKEN OR DEAD BRANCHES. SOME INTERIOR TWIGS AND LATERAL BRANCHES MAY BE PRUNED; HOWEVER, DO NOT REMOVE THE TERMINAL BUDS OF THE BRANCHES THAT EXTEND TO THE EDGE OF THE CROWN. MAINTAIN PROPER TREE FORM. DO NOT APPLY TREE PAINT TO CUTS.
- 4. REMOVE ALL DEBRIS FROM PLANTING HOLE PRIOR TO TREE PLACEMENT.
- 5. STAKING OF TREE TO BE CONFIRMED/ APPROVED BY PROJECT LANDSCAPE ARCHITECT OR CITY OF KAMLOOPS.
 6. REMOVE STAKES NO LATER THAN THE END OF FIRST GROWING SEASON AFTER PLANTING.
- 7. MULCH TO BE 50mm MINUS DOUGLAS FIR OR HEMLOCK BARK CHIPS AND FINES OR PINE CHIPS AND FINES OR COMBINATION OF FIR, HEMLOCK AND PINE.

NOT TO SCALE

4	DEC2022	REVIEWED AND UPDATED 2022	TL	JDh
3	MAY2022	REVIEWED AND UPDATED 2022	IP	JDh
2	FEB2019	REVIEWED AND UPDATED 2019	DAR	JDh
No.	DATE	REVISION DESCRIPTION	BY	APP

TREE PLANTING DETAIL (100 CALIPER OR LESS)

